## Spill Prevention Control and Countermeasure Inspection Findings, Alleged Violations, and Proposed Penalty Form

(Note: Do not use this form if there is no secondary containment)


These Findings, Alleged Violations and Penalties are issued by EPA Region 6 under the authority vested in the Administrator of EPA by Section 311(b)(6)(B)(I) of the Clean Water Act, as amended by the Oil Pollution Act of 1990

Company Name	Docket Number:	
Cook Composites + Polymens	O P A 5	
Facility Name	Date	
MARCHALL FACILITY	O P A Date  8/12/98	
Address	Inspection Number	
5851 FM 1998	F Y - I N S P -	
City:	Inspectors Name:	
MARSHALL	KANDY (OREEN	
State: Zip Code:	EPA Approving Official:	
TX 75672		
Contact:	Enforcement Contacts:	
Bill Tiller	James Graham Phone Number: (214)665-2272 Roger Hartung Phone Number: (214)665-8561	
Summa	ary of Findings	
(Bulk S	storage Facilities)	
GENERAL TOPICS: 112.3(d), (e); 112.5(a), (b), (c); 112.7 (b), (c), (d) (When the SPCC Plan review penalty exceeds \$1,000.00 enter only the minimum allowable of \$1,000.00.)		
No Spill Prevention Control and Countermeas	ure Plan	
Plan not certified by a professional engineer		
Plan not maintained on site (applies if facility is manned at least eight (8) hours per day)		
Plan not available for review		
No evidence of three-year review of plan by ov	vner/operator	
No plan amendment(s) if the facility has had a change in: design, construction, operation, or maintenance which affects the facility's discharge potential		
Amendment(s) not certified by a professional e	engineer	
Inadequate or no prediction of equipment failur	re which could result in discharges	
Plan does not discuss appropriate containment	diversionary structures equipment	

Clai	ming installation of appropriate containment/diversionary structures is impractical but:
	No contingency plan
	No written commitment of manpower, equipment, and materials
2	Written Procedures and Inspection Records 112.7(e)(8)
	Inspections required by 40 CFR Part 112 are not in accordance with written procedures developed for the facility
	Written procedures and a record of inspections are not signed by facility supervisor
	Written procedures and a record of inspections are not made part of the plan
	Written procedures and a record of inspections are not maintained for three years
	Personnel Training and Spill Prevention Procedures 112.7(e)(10)
	No training on the operation and maintenance of equipment to prevent discharges
	No training on the applicable laws, rules, and regulations
	No designated person responsible for spill prevention
	Spill prevention briefings are not scheduled and conducted periodically
	Plan has inadequate or no discussion of personnel and spill prevention procedures
	FACILITY DRAINAGE, ONSHORE (excluding Production Facilities) 112.7(e)(1)
	Valves used to drain diked areas are not of manual, open-and-closed design (note: flapper-type valves should not be used).
	Pumps or ejectors not manually activated when diked storage areas drained
	Drainage from undiked areas not into ponds, lagoons, or catchment basins, or no diversion systems to return spills to the facility.
	Plan has inadequate or no discussion of facility drainage
	BULK STORAGE TANKS (excluding Production Facilities) 112.7(e)(2)
	Material and construction of tanks not compatible to the material stored and the conditions of storage such as pressure and temperature.
	Secondary containment appears to be grossly inadequate.
	Materials of construction are not sufficiently impervious
	Excessive vegetation which affects the integrity of the containment system

	Walls of containment system are slightly eroded or have low areas	
Whe	en drainage from diked areas is to a storm drain, open water course, or lake or pond:	
	Bypass valve not normally sealed closed	
	Runoff rain water not inspected and/or will cause a harmful discharge as defined in 40 CFR 110.	
	Bypass valve is not opened and resealed under responsible supervision	
	Adequate records of drainage events are not maintained	
	Underground tanks are not protected from corrosion or are not subjected to regular pressure testing.	
	Partially buried tanks do not have buried sections protected from corrosion.	
	Aboveground tanks not subject to periodic integrity testing, such as visual, hydrostatic, and nondestructive methods, etc.	
	Outside of tank not frequently observed for signs of deterioration, leaks which might cause a spill, or accumulation of oil inside diked area.	
	Steam return /exhaust of internal heating coils which discharge into an open water course not monitored, passed through a settling tank, skimmer, or other separation system.	
	Records of inspections of aboveground tanks are not maintained.	
	Tanks are not "fail-safe" engineered:	
	No audible or visual high liquid level alarm, or	
	No high-level pump cutoff devices set to stop flow at a predetermined tank content level, or	
	No direct communications between tank gauger and pumping station, or	
	No fast response system for determining liquid levels, such as computers, telepulse, or direct vision gauges.	
	No testing of liquid level sensing devices to ensure proper operation	
	Disposal facilities which discharge plant effluents directly to navigable waters are not monitored frequently to detect oil spills	
	Visible oil leaks resulting in accumulations of oil in diked areas are not promptly corrected	
	Mobile or portable storage tanks are not positioned to prevent spilled oil from reaching navigable water, or are in area subject to flooding.	
	Secondary containment inadequate for mobile or portable storage tanks	
	Plan has inadequate or no discussion of bulk storage tanks	
FACILITY TRANSFER OPERATIONS, PUMPING, AND IN-PLANT PROCESSES, ONSHORE (excluding Production Facilities) 112.7(e)(3)		
	Buried piping not corrosion protected with protective wrapping, coating, or cathodic protection.	

	Corrective action not taken on buried piping when corrosion damage found
	Terminal connections at transfer points on not-in-service or standby pipelines are not capped or blank-flanged and marked as to origin
	Pipe supports are not properly designed to minimize abrasion and corrosion, and allow for expansion and contraction.
	Aboveground valves and pipelines are not inspected regularly
	Periodic pressure testing of the valves and pipelines is not conducted
	Vehicle traffic not warned verbally or by appropriate signs of aboveground piping.
	Plan has inadequate or no discussion of facility transfer operations, pumping, and in-plant processes.
FAC	ILITY TANK CAR AND TANK TRUCK LOADING/UNLOADING RACK, ONSHORE 112.7(e)(4)
	Inadequate secondary containment, and/or rack drainage does not flow to catchment basin, treatment system, or quick drainage system
	Containment system does not hold at least the maximum capacity of the largest single compartment of any tank car or tank truck
	There is no interlocked warning light, physical barrier system, or warning signs to prevent vehicular departure before complete disconnect from transfer lines
	There is no inspection of lowermost drains and all outlets prior to filling and departure of any tank car or tank truck.
	Plan has inadequate or no discussion of facility tank car and tank truck loading/unloading rack.
	Facility not fully fenced and entrance gates are not locked and/or guarded when plant is unattended or not in production.
SEC	URITY (excluding Production Facilities) 112.7(e)(9)
	Master flow and drain valves that permit direct outward flow of tank's contents to the surface are not secured in closed position when in a non-operating or standby status.
	Starter controls on pumps are not locked in the "off" position or located at a site accessible only to authorized personnel when pumps are not in a non-operating or standby status.
	Loading and unloading connection(s) of pipelines are not capped or blank-flanged when not in service.
	Facility lighting not commensurate with the type and location of facility to facilitate the discovery of spills during hours of darkness and to deter vandalism.
	Plan has inadequate or no discussion of facility security.



## SPCC - EXPEDITED FIELD ENFORCEMENT PROGRAM

Owner/Operator: Cook Composites ? Polymers number: 980764
Phone number: (903) 938 - 9571
Address: Mail: Rt. 6 Box 615 Mushall, TX 75672
physical: 5851 FM Road 1998
Contact: Bill Tiller Plant M. Supervisor  Contact phone number: (403) 939 34 RG
Contact phone number: (403) 639 34 /CG
Date of contact:
Date and time of scheduled inspection: 8/12/98 1:00 pm
SPCC Plan: Yes No
Tank battery location: N 32° 32.701′ W 94° 17.756′
From the intersection of Loop 390 and Hung 43 travel
South on Loop 390 to FM Rd. 1998 (a.K.a. Scottsville Road)
1 turn onto FM 1998 and travel 1/2 - 1 mile, Cook will
be on the (L) hand side of the 1000
Comments:
8/4/98 13:05 START Whilefield could not get the
man who answered the phone to tell whether or
not there was any type of oil or oil products on
site.

escycled paper

SITE NAME: N all/Longview SPCC TDD#: S06-9802-008 PHOTO#: 104 dOTOGRAPHER/WITNESS: Green/Hood

DATE: 08/12/98 TIME: 1330 DIRECTION: s

Cook Polymer heat transfer storage tank standing water in secondary

containment



SITE NAME: Marshall/Longview SPCC TDD#: S06-9802-008 PHOTO#: 105 PHOTOGRAPHER/WITNESS: Green/Hood

DATE: 08/12/98 TIME: 1330 DIRECTION: w

staining from product on top of tank



SITE NAME: SPCC Recon for Gregg Co. TDD#:\S06-9\u00e9\u00e9-008 PHOTO#: 107 PHOTOGRAPHER/WITNESS: Wakefield/Green

DATE: 07/29/98 TIME: 1213 DIRECTION:-W
Overview of Cook Composites and Polymers



SITE NAME: SPCC Recon for Gregg Co. TDD#: S06-9802-008 PHOTO#: 108-PHOTOGRAPHER WITNESS: Wakefield/Green DATE: 07/29/98 TIME: 1213 DIRECTION: W

Overview of Cook Composites and Polymers



SITE N :: Marshall/Longview SPCC TDD#: S06-9802-000 PHOTO#: 106 PHOTOGRAPHER/WITNESS: Green/Hood

DATE: 08/12/98 TIME: 1335 DIRECTION: s

overview of heat transfer tank

